



THE UNITED KINGDOM VEHICLE APPROVAL AUTHORITY

COMMUNICATION CONCERNING THE APPROVAL GRANTED <sup>(1)</sup>/ APPROVAL EXTENDED (1)/ APPROVAL-  
REFUSED (1)/ APPROVAL WITHDRAWN (1)/ PRODUCTION DEFINITELY DISCONTINUED (1) OF A  
REPLACEMENT BRAKE DISC OR A REPLACEMENT BRAKE DRUM PURSUANT TO REGULATION NO. 90.02



Approval No: 90R-02C0888/13917

Extension No: 0

Reason(s) for Extension: Not Applicable

1 Applicant's name and address:

Meritor Aftermarket  
Switzerland AG,  
Neugutstrasse 89,  
8600 Dubendorf,  
Switzerland

2. Manufacturer's name and address

Meritor Aftermarket  
Switzerland AG,  
Neugutstrasse 89,  
8600 Dubendorf,  
Switzerland

3 Make and type of brake disc/drum:

Meritor Aftermarket  
Interchangeable Disc Rear (Top Hat/Vented/Pillar)  
MBR5100, MBR5066, MBR5070, MBR5097,  
MBR5013, MBR5012, MBR5092, MBR6025

4 Vehicles/axles/brakes for which the replacement brake disc or a replacement brake drum is approved:

See Manufacturers Documents

Job Number VSN254743



5 Submitted for approval on: 26 November 2012

6 Technical service responsible for approval tests: Vehicle Certification Agency

6.1. Date of test report: 05 September 2012

6.2. Number of test report: VSN254743

7 Approval ~~GRANTED/REFUSED/EXTENDED/WITHDRAWN~~<sup>(4)</sup>

8 Place: BRISTOL

9 Date: 13 JUNE 2013

10 Signature:



A. W. STENNING  
Head of Technical and Quality Support Group

11. Annexed to this communication is a list of documents in the approval file deposited at the administrative services having delivered the approval and which can be obtained upon request.

(1) ~~Strike out~~ what does not apply.

Job Number VSN254743

